

PAVEMENT REHABILITATION TECHNIQUES: Applying Reasonableness & Avoiding Pitfalls

MIKE MALONEY, PE



LINDSI HAMMOND, PE

Project Level Evaluation

Goals:

- Develop recommendations that are:
 - Cost effective solutions
 - Feasible
 - Managed risk



Project Level Evaluation

Goals:


- Manage Expectations
 - Communication – Aligning Goals
 - PMS Output
 - Expected Performance



Project Level Evaluation

Methodology:

- Reconnaissance and As-Built Review
 - Testing and exploration plan
 - Traffic control plan



Project Level Evaluation

Methodology:

- Field Exploration and Testing
 - Number, location and type of explorations
 - FWD testing frequency
 - GPR
 - Visual survey

Project Level Evaluation

Methodology:

- Traffic Loading Estimate
 - Peak Hour Counts
 - ADT/percent trucks
 - Classified Counts
 - Tube counts
 - Video counts
 - Transit Buses



Project Level Evaluation


Methodology:

- Pavement structural analysis
 - Analysis units and backcalculation models
 - Backcalculation analysis
 - Overlay and inlay analysis
 - AASHTO input parameters

Project Level Evaluation

Methodology:

- Project Recommendations
 1. Structural requirements
 2. Grade constraints
 3. Reflective cracking



We can't solve
problems with
the same
thinking we
used when we
created them

Typical Structural Improvements

Overlay is placed in 2 to 3-in. lifts above the existing pavement surface with an increase in grade equal to the overlay thickness.

Inlay is removal of a portion of the existing asphalt concrete (by milling) and replacement with new asphalt concrete, with no increase in grade.



Mill and Overlay is removal of a portion of the existing asphalt concrete and placement of new asphalt concrete that results in an increase in grade.

Partial Depth Reconstruction is removal of the entire thickness of existing asphalt concrete and placement of new asphalt concrete on top of the existing aggregate base layer.



Full Depth Reconstruction is replacement of the existing pavement structure with a new pavement structure and may include construction on compacted or undisturbed subgrade, aggregate or mechanical stabilization, treated subgrade and full depth reclamation (FDR).

Structural Strengthening - Overlay



After Rehab



Structural Strengthening - Inlay




Structural Strengthening – Mill + Overlay



Project Level Evaluation

Methodology:

- Project Recommendations
 1. Structural requirements
 2. Grade constraints
 3. Reflective cracking




We can't solve
problems with
the same
thinking we
used when we
created them

Grade Constraints




Curbs and Driveways

Grade Constraints



Grade Constraints



Grade Constraints



Curb and gutter

Grade Constraints



PCC bike lanes

Grade Constraints



Curb ramps

Grade Constraints



Excessive crown

Grade Constraints




Grade Constraints



Project Level Evaluation

Methodology:

- Project Recommendations
 1. Structural requirements
 2. Grade constraints
 3. Reflective cracking




We can't solve
problems with
the same
thinking we
used when we
created them

Reflective Cracking



Reflective Cracking




Case Study

Avoiding Pitfalls When Moving From
PMS Output → Project Recommendations

PMS Output

Segment	Project Location	Project Year	Street Classification	PCI	Decision Tree M&R Recommendation
7	Alameda	2016	Collector	62	2" Overlay
5-6	Aviation	2016	Collector	63	2" Overlay
1-3	Edenbower	2016	Arterial/ Collector	63	2" Overlay
4	Rennan	2016	Collector	62	2" Overlay
8	Stewart	2016	Arterial	58	3-4" Grind/Inlay

Project Level Evaluation




Project Recommendations

1. Structural requirements
2. Grade constraints
3. Reflective cracking

Project Level Evaluation - Edenbower



Visual Survey



Project Level Evaluation - Edenbower



Project Level Evaluation - Edenbower



Project Level Evaluation - Edenbower



Project Level Evaluation - Edenbower




FWD Testing - Edenbower



FWD Results - Edenbower

Figure 1E - 9-Kip Deflection Profile



FWD Analysis - Edenbower

Test No.	Test Station	Dir	Unit	D0, mils	Controlling Overlay, in.	Controlling Overlay above the Milled Surface with 2-in. of Milling, in.
1	0+00	SB	Repair	28.93	4.57	5.77
2	1+50	SB	Repair	21.03	2.32	3.98
3	3+00	SB	1	15.41	0.63	2.49
4	4+50	SB	1	17.29	0.90	2.40
5	6+00	SB	1	21.76	1.85	3.33
6	7+79	SB	Repair	31.02	4.40	5.66
7	9+01	SB	1	22.92	3.07	4.49
8	10+50	SB	2	15.49	0.28	2.36
9	12+00	SB	2	16.01	0.60	2.79

FWD Analysis - Edenbower

Statistical Summary					
Structural Unit #	From	To	Average D0, mils	Average Controlling Overlay, in.	Average Controlling Overlay above the Milled Surface with 2-in. Mill Depth, in.
Repair	0+00	12+00	25.05	3.18	4.59
1	0+75	9+75	18.04	1.64	3.31
2	10+50	12+00	16.44	0.59	2.40


Rehabilitation Recommendation

- Localized Dig Out Repairs
 - 5" AC
- 2" Mill
 - Tapered from 2" at the edge of travel lane to 3" at the curb
- 3" Overlay – This will raise the grade 1" in the travel lanes

Project level Evaluation - Alameda



Project level Evaluation - Alameda



Roseburg 2016 Pavement Rehab
GRI Project No. 5829
B-16

Project level Evaluation - Alameda



Project level Evaluation - Alameda




FWD Testing - Alameda



FWD Testing - Alameda

Figure 1H - 9-Kip Deflection Profile



FWD Analysis - Alameda

Test No.	Test Station	Dir	Unit	D0, mils	Overlay Thickness above Existing Pavement, in.	Overlay Thickness above the Milled surface with 3.5-inch milling Depth
1	0+20	EB	1	7.23	zero	zero
2	1+20	EB	1	8.81	zero	zero
3	2+20	EB	1	5.9	zero	zero
4	2+89	EB	1	6.03	zero	zero
5	4+20	EB	1	7.42	zero	zero
6	5+20	EB	1	5.1	zero	zero
7	6+20	EB	1	5.45	zero	zero
8	7+20	EB	1	3.52	zero	zero
9	8+20	EB	1	7.21	zero	zero
10	8+20	WB	1	6.68	zero	zero

FWD Analysis - Alameda

Statistical Summary						
Structural Unit #	From	To	Dir	Average D0, mils	Average Overlay, in.	Average Overlay above the Milled Surface (3.5-in. Mill Depth), in.
1	0+20	8+20	Both	5.79	zero	zero

Rehabilitation Recommendation

- No Strengthening Required
- Surface Rehabilitation Required due to Extensive Top-Down Random Cracking
- 4" Mill
- 4" Inlay
 - 2- 2" Lifts

Case Study

Applying Reasonableness in Your
Project Recommendations

30th Ave

4- Lane, 2-Way AC Surface Roadway






Eastbound Lane

30th Ave



Westbound Lane

Visual Survey



LEGEND


- HIGH SEVERITY ALLIGATOR CRACKING
- MEDIUM TO HIGH SEVERITY ALLIGATOR CRACKING
- MEDIUM SEVERITY ALLIGATOR CRACKING




PAVEMENT CONDITION MAP
(E 30th AVENUE)



FWD & Coring



FWD Results



Rehabilitation Recommendation

Outer Lanes

- Partial Depth Reconstruction due to Significant % of Fatigue Cracking

Inner Lanes

- No Strengthening Required
- 2" Overlay/Inlay to Rehabilitate the Surface



Wilshire Dr.



Wilshire Dr.




Visual Survey



LEGEND

- HIGH SEVERITY ALLIGATOR CRACKING
- MEDIUM TO HIGH SEVERITY ALLIGATOR CRACKING
- MEDIUM SEVERITY ALLIGATOR CRACKING
- MEDIUM SEVERITY PATCH
- LOW SEVERITY PATCH




PAVEMENT CONDITION MAP
(WILSHIRE LANE)



Coring



FWD Results



Rehabilitation Recommendation

Western Portion

- Reconstruction due to Significant % of Fatigue Cracking and Patching

Eastern Portion

- 2" Mill
 - Tapered from 2" at the edge of travel lane to 3" at the curb
- 3" Overlay – This will raise the grade 1" in the travel lanes

Thank You!

MIKE MALONEY, PE
mmaloney@gri.com

LINDSI HAMMOND, PE
lhammond@gri.com

(503) 641 – 3478

